


- 9 Connect both jumpers together using the appropriate mating adapter. See below the interconnection schematic.



4. Perform ORL and Loopback IL Referencing

- 1 Touch the **FCOMP** tab
- 2 Press the soft key **References** to enter the reference menu.
- 3 Press the soft key **Take Refs** in order to enter the referencing wizard.
- 4 Press **Loopback** key to start referencing process for ORL and Insertion Loss
- 5 Repeat above steps 5 to 8 for loopback ORL/IL referencing.



8000 V2 PLATFORM QUICK CARD

FIBER CHARACTERIZATION SCRIPT

IL/ORL REFERENCING PROCEDURE

The following procedure describes how to perform an Insertion Loss (IL) and Optical Return Loss (ORL) referencing with the use of an MTAU and a FiberComplete module into a T-BERD/MTS 8000 V2. This measurement is done to ensure that the IL and ORL of the fiber jumpers are taken into account for an accurate qualification of the fiber to test.

Please read the entire procedure BEFORE starting.

1. Inspect and clean connectors

Before connecting a fiber into a test module, inspect and clean the module bulkhead and the fiber jumper connectors.



Use the P5000i video inspection scope to verify the connector quality.

Use appropriate cleaning material (e.g. IBC™ cleaner, cotton swab, dust air sprays, etc...) and re-inspect to confirm.

2. IL/ORL referencing with the integrated FiberComplete® solution

- 1 Connect a fiber jumper to the MTAU COM port of T-BERD/MTS 8000 V2 and one to the test port of the module of the T-BERD/MTS 6000A.

Refer to Fiber Characterization Getting Started Quick Card for proper module interconnections.

- 2 Press to turn both units on and wait the completion of auto-test (45 sec.).

Activate the FCOMP function on both units

- 1 Press the hard key and light the icon with your finger or stylus.
- 2 Press the hard key and touch the MTAU tab of the 8000 V2 unit.
- 3 Press the soft key until OUT A is selected on the 8000 V2 unit.

3. Perform ORL and side by side IL Referencing

- 1 Touch the **FCOMP** tab .
- 2 Press the soft key to enter the reference menu.
- 3 Press the soft key in order to enter the referencing wizard.
- 4 Press **Side/Side** key to start referencing process for ORL and side by side Insertion Loss .
- 5 When prompt, connect the test jumpers from the 8000V2 COM port to the mainframe power meter and from the 6000 test module to mainframe power meter, as shown below

Mainframe Power Meter



Mainframe Power Meter

MTAU 2

OTDR/FiberComplete module

- 6 Press OK to measure emitted power level.

- 7 When prompt, disconnect the test jumpers from the mainframe power meters and connect the non-reflective terminator to the end of each test jumper, as shown below

Mainframe Power Meter



Mainframe Power Meter

Non-reflective termination

- 8 Press OK to perform zero ORL referencing.