How to highlight the Cursor values - Distance and - Level and how to suppress this information in the display of the MTS-2000

If you want to not display the Information lines for the cursors in a report, you need to switch it off in the result menu before you generate a report.