

Product Information Letter

IFF-45TS Software/Firmware Update

Version 11.0

VIAVI Part Number: 72438

This Product Information Letter (PIL) informs current users of the IFF-45TS, part number 72438, that a new a new Mode 5 software/firmware revision is available. Version 11.0 software/firmware provides improved performance and additional features for Type A Crypto operation. Please contact the factory for additional details. Version 11.0 software/firmware consists of the following file versions:

HOST Version:	3.721
DSP Version:	2.735
FPGA Version:	2.135
RF FPGA Version:	0.036
RIO Version:	1.090

Note: the RF FPGA Version should be 0.036 or higher. If not, please contact the VIAVI service center at 800-835-2350 before performing this update.

This IFF-45TS software/firmware update is only applicable to IFF-45TS test equipment part number 72438, the IFF-45TS variant that is mode 5 capable. It will not install on IFF-45TS-A test equipment part number 72439.

This new software/firmware is AIMS certified as version 11.0 and is available through our customer service department as part number 89898 revision AE. This update CD is free of charge and includes software/firmware installation instructions; However, a purchase order for this part number is required for compliance with ITAR regulations.

To order the software/firmware update CD, email at GER.neworders@viavisolutions.com. For any additional technical questions email techsupport.avcomm@viavisolutions.com or contact VIAVI Customer Service at (001) 800-835-2350.